

VOLVO P1800 S/E

BOOT LID, TAILGATE, TRUNK LID

Rusty boot lids were and still are a nagging issue on the Volvo P1800. For many years now, boot lids have been in short supply on the spare parts market, so that the existing parts often require extensive repair during a restoration. That's why we decided to manufacture the tailgate from scratch.

The BASTUCK tailgates are made of galvanised deep-drawn sheet metal and additionally primed to a high standard. This means that rust will not have a chance with this part in the future. The high-quality tools used for production guarantee that the new trunk lids are in no way inferior to the original Volvo parts in terms of fitting accuracy and quality.



- » **made from galvanised deep-drawn sheet metal**
- » **high-quality primer**
- » **perfect fitting accuracy**

KA27VOP1800

Article No.	Description	Price EUR
KA27VOP1800 (Reference No.*: 664199)	Boot lid (P1800 S/E)	687,23

Price incl. 19% VAT

* The ref. number(s) are only indicated to assign technical characteristics and their possibilities of use.

They are not indicated to claim that they are equivalent, e.g. in terms of origin, material characteristics or durability.